Division of Health Care Facilities STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING 01 - MAIN BUILDING 01 B. WING TN4702 11/14/2011 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 5837 LYONS VIEW PIKE BRAKEBILL NURSING HOME INC. KNOXVILLE, TN 37919 SUMMARY STATEMENT OF DEFICIENCIES (X4) ID PROVIDER'S PLAN OF CORRECTION ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL (X5)PREFIX **PREFIX** (EACH CORRECTIVE ACTION SHOULD BE COMPLETE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG CROSS-REFERENCED TO THE APPROPRIATE TAG DEFICIENCY) N 853 1200-8-6-.08(23) Building Standards N 853 What corrective action will be accomplished that facility failed to have all dirty areas well (23) A negative air pressure shall be maintained ventilated with negative air pressure. in the soiled utility area, toilet room, janitor 's Volunteer Mechanical was contacted on 11closet, dishwashing and other such soiled 15-2011 and work order given to have exhaust spaces, and a positive air pressure shall be fans in all laundry rooms and equipment room maintained in all clean areas including, but not on blue wing. limited to, clean linen rooms and clean utility rooms. How the facility will identify areas having the potential to be affected by the deficient practice. The facility will make sure that any new areas made for dirty use have negative This Rule is not met as evidenced by: pressure or exhaust. Based on observation and interview, the facility failed to assure dirty areas were ventilated and at What measures will be put into place to ensure a negative air pressure. the deficient practice does not recur. The The findings include: maintenance department will monitor all Observation and interview with the Maintenance exhaust ventilation fans for proper working Director, on November 14, 2011 at 10:20 a.m. condition (see monitoring form, work orders confirmed four (4) of four (4) laundry areas were and contract attached). Installation was not provided with an exhaust in the soiled linen completed on 11-22-2011. area. Observation and interview with the Maintenance How the corrective action will be monitored Director, on November 14, 2011 at 10:50 a.m. to assure that deficient practice does not recur. confirmed the wheelchair equipment room across The maintenance department will monitor and from room 113 was used to charge equipment document weekly that negative pressure and had two (2) battery chargers exhaust fans are working properly and maintenance supervisor will report working order in QI bi-annually times two, then yearly thereafter. QI team consists of Medical Director, DON, ADON, Nurse Chart Auditor, MDS Coordinators, Activity Director, Rehab Manager, Dietary Manager, Medical Records Director, Social Services, Housekeeping Supervisor and Maintenance Supervisor, and Consulting Pharmacist. 1-22-1 Division of Health Care Facilities Wilkerson TITLE assistar LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE STATE FORM

BIY621